

August 4, 2014



U.S. Department
of Transportation

East Building, PHH-30
1200 New Jersey Avenue S.E.
Washington, D.C. 20590

**Pipeline and Hazardous
Materials Safety Administration**

DOT-SP 16153
(FIRST REVISION)

EXPIRATION DATE: December 31, 2014

(FOR RENEWAL, SEE 49 CFR § 107.109)

1. **GRANTEE:** Trailers y Tanques de Aluminio S.A. de C.V.
Mexico City, Mexico
(U.S. Agent: Kirstein & Young, PLLC,
Washington, D.C.)
2. **PURPOSE AND LIMITATION:**
 - a. This emergency special permit authorizes the marking, sale and use of non-DOT specification cargo tank motor vehicles which meet the requirements for a DOT specification 407 cargo tank motor vehicle, except that the ring stiffeners are not in compliance with 178.345-7(d). This special permit provides no relief from the Hazardous Materials Regulations (HMR) other than as specifically stated herein. The most recent revision supersedes all previous revisions.
 - b. The safety analyses performed in the development of this special permit only considered the hazards and risks associated with the transportation in commerce.
3. **REGULATORY SYSTEM AFFECTED:** 49 CFR Parts 106, 107 and 171-180.
4. **REGULATIONS FROM WHICH EXEMPTED:** 49 CFR §§ 178.345-7(d) in that a non-continuous ring stiffener used as circumferential reinforcement is not authorized, except as provided herein.
5. **BASIS:** This emergency special permit is based on the application of Trailers y Tanques de Aluminio S.A. de C.V. dated April 24, 2014 submitted in accordance with § 107.117 and a determination that it is necessary to prevent significant economic impact.

6. HAZARDOUS MATERIALS (49 CFR § 172.101):

Hazardous Materials Description			
Proper Shipping Name	Hazard Class/ Division	Identifi- cation Number	Packing Group
Class 3 hazardous materials authorized in DOT specification 407 cargo tank motor vehicles	3	Various	Various

7. SAFETY CONTROL MEASURES:

- a. No new manufacture is authorized after April 24, 2014.
- b. PACKAGING - The authorized packaging is a non-DOT specification cargo tank motor vehicle (CTMV) conforming with all regulations applicable to a DOT specification 407, except that the ring stiffeners are constructed of alternative materials (6061-T6) and are not in compliance with 178.345-7(d). The ring stiffeners used as circumferential reinforcement of the tank, are not continuous. The ring stiffener, as described in Tytal's April 24, 2014 application, have an approximate 1.5" gap at the bottom dead center of the ring.
- c. This special permit only authorizes the CMTV's marked with VIN numbers listed in Appendix A of this permit.

d. REQUALIFICATION:

- (i) The cargo tanks listed in Appendix A must be subjected to and successfully pass a benchmark (initial) inspection prior to marking the special permit number on the tank. The benchmark inspection must be in accordance with § 180.407(c) to the requirements for a DOT specification 407 cargo tank.
- (ii) In addition to the benchmark inspection the 1.5" gap area must be non-destructive tested (e.g. magnetic particle, dye penetrant or other means) to ensure the detection of cracks in the ring stiffener to shell, ring stiffener assembly, and other welds in the gap location; defects in the gap location; and other flaws

August 4, 2014

recognized by the examination. The initial measurement of the gap in the ring stiffener must be recorded and maintained by the owner.

(iii) Periodic requalification (after the benchmark inspection) must be in accordance with § 180.407 to the requirements of a DOT specification 407 cargo tank except that:

- (1) The external visual inspections must be performed every 6-months from the date of the benchmark inspection.
 - (2) During the external visual inspection the cargo tank facility must measure the ring stiffener gap to determine if expansion has occurred from the benchmark measurement.
 - (3) The internal visual inspection must be performed yearly from the date of the benchmark inspection.
 - (4) The non-destructive tests and inspections in paragraph (ii) must to be performed every 6 months from the date of the benchmark inspection.
- (iv) When the results of the inspection determine the ring stiffener gap has expanded greater than $\frac{1}{4}$ inch from the benchmark measurement, the cargo tank must be taken out of hazardous materials service and all specification markings must be removed or obliterated.
- (v) Prior to being returned to hazardous materials service, the cargo tank motor vehicle must be brought into full conformance with Part 178 which contains the requirements for DOT specification 407 cargo tank motor vehicles. If repaired, the tanks must be repaired by an R-stamp facility.

e. OPERATIONAL CONTROLS:

(i) Recordkeeping:

- (1) The benchmark inspection results and most recent periodic inspection results (internal and external visual inspection, NDT and gap measurement) must be maintained by the tank

August 4, 2014

owner and the requalification facilities for the service life of the cargo tank and be made available upon request to DOT personnel and submitted to:

FMCSA.PHMSASP-AP@DOT.GOV (email); or

USDOT
FMCSA/MC-ECH (Attention: Division Chief)
202-366-3621 (Fax); or

USDOT
FMCSA/MC-ECH (Attention: Division Chief)
1200 New Jersey Ave SW
Washington, DC 2059

- (2) The above referenced submission must include documentation of all repairs recommended or performed subsequent to the inspection. The inspection results must be submitted by the tank owner and the cargo tank facilities no later than 30 days after the completion of repairs performed on the tanks marked in accordance with this special permit.
- (3) The benchmark inspection report must be provided to the cargo tank facility prior to the facility conducting periodic inspection under the terms of this special permit.
- (4) Each cargo tank motor vehicle inspected under the terms of this special permit must be marked in accordance Part 180 and the external visual inspection must include the month date. Ex. V xx-xx where the xx is replaced with the year and month.
 - (ii) MARKING: Each tank must be plainly and permanently marked "DOT-SP 16153" next to the DOT markings on the DOT specification plate.

8. SPECIAL PROVISIONS:

- a. In accordance with the provisions of Paragraph (b) of § 173.22a, persons may use the packaging authorized by this special permit for the transportation of the hazardous materials specified in paragraph 6, only in conformance with the terms of this special permit.

August 4, 2014

b. A person who is not a holder of this special permit, but receives a packaging covered by this special permit, may reoffer it for transportation provided no modification or change is made to the packaging and it is offered for transportation in conformance with this special permit and the HMR.

c. A current copy of this special permit must be maintained at each facility where the CTMV is offered, reoffered, requalified, inspected, or repaired.

d. Each packaging manufactured under the authority of this special permit must be either (1) marked with the name of the manufacturer and location (city and state) of the facility at which it is manufactured or (2) marked with a registration symbol designated by the Office of Hazardous Materials Special Permits and Approvals for a specific manufacturing facility.

e. A current copy of this special permit must be maintained at each facility where the packaging is manufactured under this special permit. It must be made available to a DOT representative upon request.

9. MODES OF TRANSPORTATION AUTHORIZED: Motor vehicle.
10. MODAL REQUIREMENTS: A current copy of this special permit must be carried aboard each motor vehicle used to transport packages covered by this special permit.
11. COMPLIANCE: Failure by a person to comply with any of the following may result in suspension or revocation of this special permit and penalties prescribed by the Federal hazardous materials transportation law, 49 U.S.C. 5101 et seq:
 - o All terms and conditions prescribed in this special permit and the Hazardous Materials Regulations, 49 CFR Parts 171-180.
 - o Persons operating under the terms of this special permit must comply with the security plan requirement in Subpart I of Part 172 of the HMR, when applicable.
 - o Registration required by § 107.601 et seq., when applicable.

August 4, 2014

Each "Hazmat employee", as defined in § 171.8, who performs a function subject to this special permit must receive training on the requirements and conditions of this special permit in addition to the training required by §§ 172.700 through 172.704.

No person may use or apply this special permit, including display of its number, when this special permit has expired or is otherwise no longer in effect.

Under Title VII of the Safe, Accountable, Flexible, Efficient Transportation Equity Act: A Legacy for Users (SAFETEA-LU)—“The Hazardous Materials Safety and Security Reauthorization Act of 2005” (Pub. L. 109-59), 119 Stat. 1144 (August 10, 2005), amended the Federal hazardous materials transportation law by changing the term “exemption” to “special permit” and authorizes a special permit to be granted up to two years for new special permits and up to four years for renewals.

12. REPORTING REQUIREMENTS: Shipments or operations conducted under this special permit are subject to the Hazardous Materials Incident Reporting requirements specified in 49 CFR §§ 171.15 – Immediate notice of certain hazardous materials incidents, and 171.16 – Detailed hazardous materials incident reports. In addition, the grantee(s) of this special permit must notify the Associate Administrator for Hazardous Materials Safety, in writing, of any incident involving a package, shipment or operation conducted under terms of this special permit.

Issued in Washington, D.C.:



for Dr. Magdy El-Sibaie
Associate Administrator for Hazardous Materials Safety
Dr. Magdy El-Sibaie
Associate Administrator for Hazardous Materials Safety

August 4, 2014

Address all inquiries to: Associate Administrator for Hazardous Materials Safety, Pipeline and Hazardous Material Safety Administration, U.S. Department of Transportation, East Building PHH-30, 1200 New Jersey Avenue, Southeast, Washington, D.C. 20590.

Copies of this special permit may be obtained by accessing the Hazardous Materials Safety Homepage at http://hazmat.dot.gov/sp_app/special_permits/spec_perm_index.htm. Photo reproductions and legible reductions of this special permit are permitted. Any alteration of this special permit is prohibited.

PO: SGrey

DOT-SP 16153 Appendix A
Cargo Tanks Manufactured in 2011

3T1L1B626BC000036
3T1L1B628BC000037
3T1L1B62XBC000038
3T1L1T62XBC000059
3T1L1T628BC000075
3T1L1T62XBC000076
3T1L1T623BC000078
3T1L1T625BC000079
3T1L1T629BC000151
3T1L1T620BC000152

DOT-SP 16153 Appendix A
Cargo Tanks Manufactured in 2012

3T1L1T62XCC000001	3T1L1TA32CC000168	3T1L1TA39CC000300	3T1L1TA32CC000350	3T1L1T62XCC000614
3T1L1T621CC000002	3T1L1TA34CC000169	3T1L1TA30CC000301	3T1L1TA34CC000351	3T1L1T621CC000615
3T1L1T623CC000003	3T1L1TA30CC000170	3T1L1TA32CC000302	3T1L1TA36CC000352	3T1L1T623CC000616
3T1L1T625CC000004	3T1L1TA32CC000171	3T1L1TA34CC000303	3T1L1TA38CC000353	3T1L1T625CC000617
3T1L1T627CC000005	3T1L1TA34CC000172	3T1L1TA36CC000304	3T1L1TA3XCC000354	3T1L1T627CC000618
3T1L1T629CC000006	3T1L1TA36CC000173	3T1L1TA38CC000305	3T1L1TA31CC000355	3T1L1T624CC000687
3T1L1T620CC000007	3T1L1TA37CC000196	3T1L1TA3XCC000306	3T1L1TA33CC000356	3T1L1T626CC000688
3T1L1T622CC000008	3T1L1TA39CC000197	3T1L1TA31CC000307	3T1L1TA38CC000370	3T1L1T628CC000689
3T1L1T624CC000009	3T1L1TA30CC000198	3T1L1TA33CC000308	3T1L1TA3XCC000371	3T1L1T624CC000690
3T1L1T620CC000010	3T1L1TA32CC000199	3T1L1TA35CC000309	3T1L1TA31CC000372	3T1L1T626CC000691
3T1L1T622CC000011	3T1L1TA35CC000200	3T1L1TA31CC000310	3T1L1TA39CC000393	3T1L1T628CC000692
3T1L1T624CC000012	3T1L1TA37CC000201	3T1L1TA33CC000311	3T1L1TA30CC000394	3T1L1T62XCC000693
3T1L1T626CC000013	3T1L1TA39CC000202	3T1L1TA35CC000312	3T1L1TA32CC000395	3T1L1T621CC000694
3T1L1T628CC000014	3T1L1TA30CC000203	3T1L1TA37CC000313	3T1L1TA34CC000396	3T1L1T623CC000695
3T1L1T62XCC000015	3T1L1TA32CC000204	3T1L1TA39CC000314	3T1L1TA36CC000397	3T1L1T625CC000696
3T1L1T621CC000016	3T1L1TA34CC000205	3T1L1TA30CC000315	3T1L1TA38CC000417	3T1L1T627CC000697
3T1L1T623CC000017	3T1L1TA3XCC000208	3T1L1TA32CC000316	3T1L1TA3XCC000418	3T1L1T629CC000698
3T1L1T625CC000018	3T1L1TA31CC000209	3T1L1TA34CC000317	3T1L1TA31CC000419	3T1L1T620CC000699
3T1L1T722CC000041	3T1L1TA38CC000210	3T1L1TA36CC000318	3T1L1TA3XCC000452	3T1L1T623CC000700
3T1L1T724CC000042	3T1L1TA3XCC000211	3T1L1TA38CC000319	3T1L1T622CC000476	3T1L1T625CC000701
3T1L1T726CC000043	3T1L1TA31CC000212	3T1L1TA34CC000320	3T1L1T624CC000477	3T1L1T627CC000702
3T1L1T728CC000044	3T1L1TA33CC000213	3T1L1TA36CC000321	3T1L1TA31CC000548	3T1L1T629CC000703
3T1L1T72XCC000045	3T1L1TA35CC000214	3T1L1TA38CC000322	3T1L1TA33CC000549	3T1L1T620CC000704
3T1L1T627CC000053	3T1L1TA37CC000215	3T1L1TA3XCC000323	3T1L1TA3XCC000550	3T1L1T622CC000705
3T1L1T629CC000054	3T1L1TA39CC000216	3T1L1TA31CC000324	3T1L1TA31CC000551	3T1L1T624CC000706
3T1L1T620CC000055	3T1L1TA30CC000217	3T1L1TA33CC000325	3T1L1TA33CC000552	3T1L1TA36CC000707
3T1L1T622CC000056	3T1L1TA32CC000218	3T1L1TA35CC000326	3T1L1TA35CC000553	3T1L1TA38CC000708
3T1L1T624CC000057	3T1L1TA34CC000219	3T1L1TA37CC000327	3T1L1TA37CC000554	3T1L1TA3XCC000709
3T1L1T626CC000058	3T1L1TA30CC000220	3T1L1TA39CC000328	3T1L1TA39CC000555	3T1L1TA36CC000710
3T1L1T628CC000059	3T1L1TA32CC000221	3T1L1TA30CC000329	3T1L1TA30CC000556	3T1L1TA38CC000711
3T1L1T624CC000060	3T1L1TA34CC000222	3T1L1TA37CC000330	3T1L1TA32CC000557	3T1L1T62XCC000712
3T1L1T626CC000061	3T1L1TA36CC000223	3T1L1TA39CC000331	3T1L1TA32CC000560	3T1L1T621CC000713
3T1L1T628CC000062	3T1L1TA38CC000224	3T1L1TA30CC000332	3T1L1TA34CC000561	3T1L1T623CC000714
3T1L1T62XCC000063	3T1L1TA3XCC000225	3T1L1TA32CC000333	3T1L1TA36CC000562	3T1L1T625CC000715
3T1L1T621CC000064	3T1L1TA31CC000226	3T1L1TA34CC000334	3T1L1TA38CC000563	3T1L1T627CC000716
3T1L1T623CC000065	3T1L1TA33CC000227	3T1L1TA36CC000335	3T1L1TA3XCC000564	3T1L1T629CC000717
3T1L1T625CC000066	3T1L1TA35CC000228	3T1L1TA38CC000336	3T1L1TA35CC000570	3T1L1T620CC000718
3T1L1T627CC000067	3T1L1TA37CC000229	3T1L1TA3XCC000337	3T1L1T624CC000575	3T1L1T622CC000719
3T1L1T629CC000068	3T1L1TA33CC000230	3T1L1TA31CC000338	3T1L1T626CC000576	3T1L1T629CC000720
3T1L1T620CC000069	3T1L1TA35CC000231	3T1L1TA33CC000339	3T1L1T628CC000577	3T1L1T620CC000721
3T1L1T627CC000070	3T1L1TA37CC000232	3T1L1TA3XCC000340	3T1L1T62XCC000578	
3T1L1T629CC000071	3T1L1TA39CC000233	3T1L1TA31CC000341	3T1L1T621CC000579	
3T1L1T620CC000072	3T1L1TA30CC000234	3T1L1TA33CC000342	3T1L1TA38CC000580	
3T1L1TA3XCC000161	3T1L1TA32CC000235	3T1L1TA35CC000343	3T1L1TA3XCC000581	
3T1L1TA31CC000162	3T1L1TA37CC000294	3T1L1TA37CC000344	3T1L1T623CC000602	
3T1L1TA33CC000163	3T1L1TA39CC000295	3T1L1TA39CC000345	3T1L1T625CC000603	
3T1L1TA35CC000164	3T1L1TA30CC000296	3T1L1TA30CC000346	3T1L1T627CC000604	
3T1L1TA37CC000165	3T1L1TA32CC000297	3T1L1TA32CC000347	3T1L1T629CC000605	
3T1L1TA39CC000166	3T1L1TA34CC000298	3T1L1TA34CC000348	3T1L1T620CC000606	
3T1L1TA30CC000167	3T1L1TA36CC000299	3T1L1TA36CC000349	3T1L1TA32CC000607	

DOT-SP 16153 Appendix A
Cargo Tanks Manufactured in 2013

3T1L1T628DC000001	3T1L1T225DC000110	3T1L1T625DC000151	3T1L1T620DC000204	3T1L1T62XDC000257	3T1L1T626CC000416
3T1L1T62XDC000002	3T1L1T622DC000110	3T1L1T627DC000152	3T1L1T622DC000205	3T1L1T621DC000258	3T1L1T622DC000172
3T1L1T621DC000003	3T1L1T227DC000111	3T1L1T629DC000153	3T1L1T624DC000206	3T1L1T623DC000259	3T1L1T624DC000173
3T1L1T623DC000004	3T1L1T624DC000111	3T1L1T620DC000154	3T1L1T626DC000207	3T1L1T62XDC000260	
3T1L1T625DC000005	3T1L1T229DC000112	3T1L1T622DC000155	3T1L1T628DC000208	3T1L1T621DC000261	
3T1L1T622DC000026	3T1L1T626DC000112	3T1L1T626DC000157	3T1L1T62XDC000209	3T1L1T623DC000262	
3T1L1TA34DC000027	3T1L1T220DC000113	3T1L1T628DC000158	3T1L1T626DC000210	3T1L1T625DC000263	
3T1L1T621DC000048	3T1L1T628DC000113	3T1L1T62XDC000159	3T1L1T628DC000211	3T1L1T627DC000264	
3T1L1T623DC000049	3T1L1T222DC000114	3T1L1T626DC000160	3T1L1T62XDC000212	3T1L1T629DC000265	
3T1L1T62XDC000050	3T1L1T62XDC000114	3T1L1T628DC000161	3T1L1T621DC000213	3T1L1T620DC000266	
3T1L1T621DC000051	3T1L1T224DC000115	3T1L1T62XDC000162	3T1L1T623DC000214	3T1L1T622DC000267	
3T1L1T623DC000052	3T1L1T621DC000115	3T1L1T621DC000163	3T1L1T625DC000215	3T1L1T624DC000268	
3T1L1T625DC000053	3T1L1T226DC000116	3T1L1T623DC000164	3T1L1T627DC000216	3T1L1T626DC000269	
3T1L1T627DC000054	3T1L1T623DC000116	3T1L1T625DC000165	3T1L1T629DC000217	3T1L1T622DC000270	
3T1L1T629DC000055	3T1L1T228DC000117	3T1L1T627DC000166	3T1L1T620DC000218	3T1L1T624DC000271	
3T1L1T620DC000056	3T1L1T625DC000117	3T1L1T629DC000167	3T1L1T622DC000219	3T1L1T626DC000272	
3T1L1T622DC000057	3T1L1T22XDC000118	3T1L1T620DC000168	3T1L1T629DC000220	3T1L1T628DC000273	
3T1L1T624DC000058	3T1L1T627DC000118	3T1L1T622DC000169	3T1L1T620DC000221	3T1L1T62XDC000274	
3T1L1T626DC000059	3T1L1T221DC000119	3T1L1T629DC000170	3T1L1T622DC000222	3T1L1T621DC000275	
3T1L1T622DC000060	3T1L1T629DC000119	3T1L1T620DC000171	3T1L1T624DC000223	3T1L1T623DC000276	
3T1L1T624DC000061	3T1L1T228DC000120	3T1L1T626DC000174	3T1L1T626DC000224	3T1L1T625DC000277	
3T1L1T626DC000062	3T1L1T625DC000120	3T1L1T628DC000175	3T1L1T628DC000225	3T1L1T627DC000278	
3T1L1T628DC000063	3T1L1T22XDC000121	3T1L1T62XDC000176	3T1L1T62XDC000226	3T1L1T62XDC000288	
3T1L1T62XDC000064	3T1L1T627DC000121	3T1L1T621DC000177	3T1L1T621DC000227	3T1L1T625DC000294	
3T1L1T428DC000065	3T1L1T221DC000122	3T1L1T623DC000178	3T1L1T623DC000228	3T1L1T627DC000295	
3T1L1T42XDC000066	3T1L1T223DC000123	3T1L1T625DC000179	3T1L1T625DC000229	3T1L1T629DC000296	
3T1L1T421DC000067	3T1L1T225DC000124	3T1L1T621DC000180	3T1L1T621DC000230	3T1L1T620DC000297	
3T1L1T423DC000068	3T1L1T227DC000125	3T1L1T623DC000181	3T1L1T623DC000231	3T1L1T622DC000298	
3T1L1T425DC000069	3T1L1T229DC000126	3T1L1T625DC000182	3T1L1T625DC000232	3T1L1T420DC000299	
3T1L1T421DC000070	3T1L1T220DC000127	3T1L1T627DC000183	3T1L1T627DC000233	3T1L1T423DC000300	
3T1L1T423DC000071	3T1L1T222DC000128	3T1L1T629DC000184	3T1L1T624DC000237	3T1L1T425DC000301	
3T1L1T425DC000072	3T1L1T224DC000129	3T1L1T620DC000185	3T1L1T422DC000238	3T1L1T427DC000302	
3T1L1T427DC000073	3T1L1T621DC000129	3T1L1T622DC000186	3T1L1T424DC000239	3T1L1T429DC000303	
3T1L1T429DC000074	3T1L1T220DC000130	3T1L1T624DC000187	3T1L1T420DC000240	3T1L1T420DC000304	
3T1L1T420DC000075	3T1L1T628DC000130	3T1L1T626DC000188	3T1L1T422DC000241	3T1L1T625DC000313	
3T1L1T422DC000076	3T1L1T62XDC000131	3T1L1T628DC000189	3T1L1T424DC000242	3T1L1T627DC000314	
3T1L1T424DC000077	3T1L1T621DC000132	3T1L1T624DC000190	3T1L1T426DC000243	3T1L1T629DC000315	
3T1L1T426DC000078	3T1L1T623DC000133	3T1L1T626DC000191	3T1L1T428DC000244	3T1L1T620DC000316	
3T1L1T629DC000086	3T1L1T625DC000134	3T1L1T628DC000192	3T1L1T42XDC000245	3T1L1T622DC000317	
3T1L1T620DC000087	3T1L1T622DC000138	3T1L1T62XDC000193	3T1L1T421DC000246	3T1L1T625DC000327	
3T1L1T622DC000088	3T1L1T624DC000139	3T1L1T621DC000194	3T1L1T423DC000247	3T1L1T627DC000328	
3T1L1T624DC000089	3T1L1T427DC000140	3T1L1T623DC000195	3T1L1T629DC000248	3T1L1T629DC000329	
3T1L1T620DC000090	3T1L1T429DC000141	3T1L1T625DC000196	3T1L1T620DC000249	3T1L1T625DC000330	
3T1L1T621DC000101	3T1L1T420DC000142	3T1L1T627DC000197	3T1L1T627DC000250	3T1L1T627DC000331	
3T1L1T623DC000102	3T1L1T422DC000143	3T1L1T629DC000198	3T1L1T629DC000251	3T1L1T629DC000332	
3T1L1T625DC000103	3T1L1T621DC000146	3T1L1T620DC000199	3T1L1T620DC000252	3T1L1T620DC000381	
3T1L1T622DC000107	3T1L1T623DC000147	3T1L1T623DC000200	3T1L1T622DC000253	3T1L1T622DC000382	
3T1L1T624DC000108	3T1L1T625DC000148	3T1L1T625DC000201	3T1L1T624DC000254	3T1L1T620BC000071	
3T1L1T229DC000109	3T1L1T627DC000149	3T1L1T627DC000202	3T1L1T626DC000255	3T1L1T622BC000072	
3T1L1T626DC000109	3T1L1T623DC000150	3T1L1T629DC000203	3T1L1T628DC000256	3T1L1T624CC000415	